

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




FIG. 1

PRIOR ART







PRIOR ART FIG. 2A




PRIOR ART FIG. 2B



PRIOR ART FIG. 2C




PRIOR ART FIG. 2D






Title: SEMICONDUCTOR DEVICE HAVING A FUSE
Inventor: Norio OKADA
Filing Date: September 11, 2003
Serial No.: 10/660,168
REPLACEMENT SHEET Docket No.: FPM-02302

PRIOR ART FIG. 3A



PRIOR ART FIG. 3B





Title: SEMICONDUCTOR DEVICE HAVING A FUSE
Inventor: Norio OKADA
Filing Date: September 11, 2003
Serial No.: 10/660,168
REPLACEMENT SHEET Docket No.: FPM-02302

PRIOR ART FIG. 4




FIG. 5

